



FEDERAL AVIATION ADMINISTRATION



FLIGHT ADVISORY GPS INTERFERENCE TESTING BLISS GPS 16-02

**7-14 September, 2016
Fort Bliss, TX**

GPS testing is scheduled as follows and may result in unreliable or unavailable GPS signal.

A. Location: Centered at 321804N1060125W or the ELP VOR 014 degree radial at 32 NM.

B. Dates and times:

7 SEP 16	1000Z – 1800Z
8 SEP 16	1100Z – 1900Z
9 SEP 16	0500Z – 1600Z
12 SEP 16	0800Z – 1600Z
13 SEP 16	2130Z – 2400Z
14 SEP 16	0001Z – 0530Z

C. Duration: Each event may last the entire requested period.

D. NOTAM INFO: NAV (BLISS GPS 16-02) GPS (INCLUDING WAAS, GBAS, AND ADS-B) MAY NOT BE AVBL WI A 046NM RADIUS CENTERED AT 321804N1060125W (ELP 014032) FL400-UNL INCREASING IN AREA WITH A DECREASE IN ALT DEFINED AS:
047NM RADIUS AT FL250
048NM RADIUS AT 10000FT
048NM RADIUS AT 4000FT AGL
056NM RADIUS AT 50FT AGL

E. Pilots are encouraged to report anomalies only when ATC assistance is required.

The time periods discussed in this advisory may be reduced or cancelled with little or no notice. Pilots are advised to check NOTAMs frequently for possible changes prior to operations in the area. NOTAMs will be published at least 24 hours in advance of any GPS tests.

